

Township Roads – Pavement Condition Rating (PCR)


Road Name: S WRIGHT ST between Route 84 & Buie Rd

Inspector: Jim Branch

Date: Apr 29, 2018

Last Maintenance Date: 2016

Last Maintenance Type: Paving



100-90	Very Good
89-75	Good
74-65	Fair
64-55	Fair to Poor
54-40	Poor
39-0	Very Poor

Distress Type	Distress Weight	Severity	Frequency	Deduct Points
Raveling:	10	None - 0	None - 0	
Bleeding:	5	None - 0	None - 0	
Patching:	5	Low - 0.3	Occasional - 0.6	0.9
Debonding / Potholes:	5	Low - 0.3	Occasional - 0.6	0.9
Rutting:	10	None - 0	None - 0	
Map Cracking:	5	Medium - 0.6	Frequent - 0.8	2.4
Base Failure:	10	None - 0	None - 0	
Settlements:	5	None - 0	None - 0	
Transverse Cracks:	10	Low - 0.4	Occasional - 0.5	2
Wheel Track Cracking:	15	None - 0	None - 0	
Longitudinal Cracking:	5	Low - 0.2	Occasional - 0.4	0.4
Edge Cracking:	5	Medium - 0.7	Frequent - 0.7	2.45
Pressure Damage Upheaval:	5	None - 0	None - 0	
Crack Sealing Deficiency:	5	None - 0	None - 0	
Total Deduct Points:				9.05
Total Structural Deduct Points:				4.85
PCR:				90.95

Notes:

Photo Documentation

Distress Type: Debonding / Potholes



Photo Documentation

Distress Type: Debonding / Potholes



Photo Documentation

Distress Type: Edge Cracking



Photo Documentation

Distress Type: Longitudinal Cracking



Photo Documentation

Distress Type: Debonding / Potholes



Photo Documentation

Distress Type: Map Cracking



Photo Documentation

Distress Type: Map Cracking